# **APPENDIX B: eCCR Certification Form (Suggested Format)**

## **Consumer Confidence Report Certification Form**

(To be submitted with a copy of the CCR)

| Water System Name:   | Elks Lodge   |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|
| Water System Number:   | 5000563  | 5000563  |  |  |  |  |  |  |  |
| was distributed on<br>appropriate notices of ava<br>information contained in   | 06-14-<br>ilability have been<br>the report is c<br>ly submitted to  | ertifies that its Consumer Confidence Report 2023 (date) to customers (and n given). Further, the system certifies that the orrect and consistent with the compliance the State Water Resources Control Board, |  |  |  |  |  |  |  |
| Certified by:  |  |  |  |  |  |  |  |  |  |
| Name: Marty Bolter   |  | Title: Water Tech  |  |  |  |  |  |  |  |
| Signature:   | 3  | Date: 06-16-2023   |  |  |  |  |  |  |  |
| Phone number: (209) 47   | 79-6801  | Δ.   |  |  |  |  |  |  |  |
| Dage by checking all items  CCR was distributed Bulletin Boards).  CCR was distributed for Electronic Deliver electronic delivery me "Good faith" efforts wincluded the following all items. | s that apply and find the strain of the strain of the consumer of the consumer of the consumer of the strain of th | delivery methods (Posted on Public delivery methods described in the Guidance or Confidence Report (water systems utilizing plete the second page).  |  |  |  |  |  |  |  |
|  |  | ons within the service area (attach zip codes  |  |  |  |  |  |  |  |
| Advertising the release)   | Advertising the availability of the CCR in news media (attach copy of press  |  |  |  |  |  |  |  |  |
|  | Publication of the CCR in a local newspaper of general circulation (attach a copy of the published notice, including name of newspaper and date  |  |  |  |  |  |  |  |  |
| ☐ Posted the CCI   | R in public places   | (Community Bulletin Boards and Office)   |  |  |  |  |  |  |  |

### **2022** Consumer Confidence Report

| Water System Name: | Elks Lodge | Report Date: | 02/08/23 |
|--------------------|------------|--------------|----------|
|--------------------|------------|--------------|----------|

We test the drinking water quality for many constituents as required by state and federal regulations. This report shows the results of our monitoring for the period of January 1 - December 31, 2022 and may include earlier monitoring data.

# Este informe contiene información muy importante sobre su agua para beber. Favor de comunicarse Elks Lodge a (209) 406-6069 para asistirlo en español.

|                                    |   |            | O , ,                     | -    |      | -              |  |  |  |
|------------------------------------|---|------------|---------------------------|------|------|----------------|--|--|--|
| Type of water source(s) in use:    | se: Groundwater Well  |            |                           |      |      |                |  |  |  |
| Name & general location of source  | of source(s): Well at 645 Charity Way Modesto, CA   |            |                           |      |      |                |  |  |  |
|                                    |   |            |                           |      |      |                |  |  |  |
| Drinking Water Source Assessment   | Drinking Water Source Assessment information: Completed in January of 2009 - see last page. |            |                           |      |      |                |  |  |  |
|                                    |   |            |                           |      |      |                |  |  |  |
| Time and place of regularly schedu | led boar  | d meetings | for public participation: |      | None |                |  |  |  |
|                                    |   |            |                           |      |      |                |  |  |  |
| For more information, contact:     | Sam He  | dge        |                           | Phor | ne:  | (209) 406-6069 |  |  |  |
|                                    |   |            |                           |      |      |                |  |  |  |

#### TERMS USED IN THIS REPORT

Maximum Contaminant Level (MCL): The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible. Secondary MCLs are set to protect the odor, taste, and appearance of drinking water.

Maximum Contaminant Level Goal (MCLG): The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs are set by the U.S. Environmental Protection Agency (USEPA).

**Public Health Goal (PHG)**: The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California Environmental Protection Agency.

Maximum Residual Disinfectant Level (MRDL): The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

#### Maximum Residual Disinfectant Level Goal (MRDLG):

The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

**Primary Drinking Water Standards (PDWS)**: MCLs and MRDLs for contaminants that affect health along with their monitoring and reporting requirements, and water treatment requirements.

**Regulatory Action Level (AL)**: The concentration of a contaminant which, if exceeded, triggers treatment or other requirements that a water system must follow.

**Secondary Drinking Water Standards (SDWS)**: MCLs for contaminants that affect taste, odor, or appearance of the drinking water. Contaminants with SDWSs do not affect the health at the MCL levels.

**Treatment Technique (TT)**: A required process intended to reduce the level of a contaminant in drinking water.

**Level 1 Assessment**: A Level 1 assessment is a study of the water system to identify potential problems and determine (if possible) why total coliform bacteria have been found in our water system.

**Level 2 Assessment**: A Level 2 assessment is a very detailed study of the water system to identify potential problems and determine (if possible) why an *E. coli* MCL violation has occurred and/or why total coliform bacteria have been found in our water system on multiple occasions.

**Variances and Exemptions**: State Board permission to exceed an MCL or not comply with a treatment technique under certain conditions.

ND: not detectable at testing limit

ppm: parts per million or milligrams per liter (mg/L)

ppb: parts per billion or micrograms per liter (µg/L)

**ppt**: parts per trillion or nanograms per liter (ng/L)

**ppq**: parts per quadrillion or picogram per liter (pg/L)

pCi/L: picocuries per liter (a measure of radiation)

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

#### Contaminants that may be present in source water include:

- *Microbial contaminants*, such as viruses and bacteria, that may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.
- *Inorganic contaminants*, such as salts and metals, that can be naturally-occurring or result from urban stormwater runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.
- Pesticides and herbicides, that may come from a variety of sources such as agriculture, urban stormwater runoff, and residential uses.
- *Organic chemical contaminants*, including synthetic and volatile organic chemicals, that are by-products of industrial and petroleum production, and can also come from gas stations, urban stormwater runoff, agricultural application, and septic systems.
- Radioactive contaminants, that can be naturally-occurring or be the result of oil and gas production and mining activities.

In order to ensure that tap water is safe to drink, the U.S. EPA and the State Board prescribe regulations that limit the amount of certain contaminants in water provided by public water systems. The U.S. Food and Drug Administration regulations and California law also establish limits for contaminants in bottled water that provide the same protection for public health.

**Tables 1, 2, 3, 4, and 5 list all of the drinking water contaminants that were detected during the most recent sampling for the constituent**. The presence of these contaminants in the water does not necessarily indicate that the water poses a health risk. The State Board allows us to monitor for certain contaminants less than once per year because the concentrations of these contaminants do not change frequently. Some of the data, though representative of the water quality, are more than one year old.

\*Any violation of an AL, MCL, MRDL, or TT is asterisked. Additional information regarding the violation is provided later in this report.

| TABLE 1 – SAMPLING RESULTS SHOWING THE DETECTION OF COLIFORM BACTERIA |                              |                                  |     |      |                              |  |  |  |
|---|------------------------------|----------------------------------|-----|------|------------------------------|--|--|--|
| Microbiological<br>Contaminants                                       | Highest No. of<br>Detections | No. of<br>Months in<br>Violation | MCL | MCLG | Typical Source of Bacteria   |  |  |  |
| E. Coli   | 0                            | 0                                | (a) | 0    | Human and animal fecal waste |  |  |  |

(a) Routine and repeat samples are total coliform-positive and either is *E. coli*-positive or system fails to take repeat samples following *E. coli*-positive routine sample or system fails to analyze total coliform-positive repeat sample for *E. coli*.

| TABLE                                 | TABLE 2 – SAMPLING RESULTS SHOWING THE DETECTION OF LEAD AND COPPER |                                |  |                              |     |     |   |  |  |  |
|---------------------------------------|---|--------------------------------|--|------------------------------|-----|-----|---|--|--|--|
| Lead and Copper (and reporting units) | Sample<br>Date  | No. of<br>Samples<br>Collected | 90 <sup>th</sup> Percentile Level Detected | No. Sites<br>Exceeding<br>AL | AL  | PHG | Typical Source of Contaminant   |  |  |  |
| Lead (ppb)                            | 07/02/21  | 5                              | < 5  | 0                            | 15  | 0.2 | Internal corrosion of household water plumbing systems; discharges from industrial manufacturers; erosion of natural deposits |  |  |  |
| Copper (ppm)                          | 07/02/21  | 5                              | 0.1  | 0                            | 1.3 | 0.3 | Internal corrosion of household<br>plumbing systems; erosion of<br>natural deposits; leaching from<br>wood preservatives      |  |  |  |

#### TABLE 3 – DETECTION OF CONTAMINANTS WITH A PRIMARY DRINKING WATER STANDARD

| Chemical or Constituent (and reporting units) | Sample<br>Date | Level<br>Detected | Range of Detections | MCL<br>[MRDL] | PHG<br>(MCLG)<br>[MRDLG] | Typical Source of Contaminant  |
|---|----------------|-------------------|---------------------|---------------|--------------------------|--|
| Nitrate as Nitrogen (ppm)                     | 2022           | 5                 | 5 - 6               | 10            | 10                       | Runoff and leaching from fertilizer use;<br>leaching from septic tanks and sewage; erosion<br>of natural deposits  |
| Barium (ppm)                                  | 05/05/21       | 0.1               |                     | 1             | 2                        | Discharge of oil drilling wastes and from metal refineries; erosion of natural deposits  |
| Arsenic (ppb)                                 | 05/05/21       | 3                 |                     | 10            |                          | Erosion of natural deposits; runoff from orchards; glass and electronics production wastes   |
| 1,2,3-Trichloropropane<br>[TCP] (µg/L)        | 2022           | 0.04*             | 0.04* - 0.04*       | 0.005         |                          | Discharge from industrial and agricultural chemical factories; leaching from hazardous waste sites; used as cleaning and maintenance solvent, paint and varnish remover, and cleaning and degreasing agent; byproduct during the production of other compounds and pesticides. |

#### TABLE 4 – SAMPLING RESULTS FOR SODIUM AND HARDNESS

| Chemical or Constituent (and reporting units) | Sample<br>Date | Level<br>Detected       | Range of Detections | MCL | PHG<br>(MCLG) | Typical Source of Contaminant  |
|---|----------------|-------------------------|---------------------|-----|---------------|--|
| Sodium (ppm)                                  |                | No Results<br>to Report |                     |     |               | Salt present in the water and is generally naturally occurring                                       |
| Hardness (ppm)                                |                | No Results<br>to Report |                     |     |               | Sum of polyvalent cations present in the water, generally magnesium and calcium, naturally occurring |

| TABLE 5 – DETECTION OF CONTAMINANTS WITH A <u>SECONDARY</u> DRINKING WATER STANDARD |                |                         |                     |      |               |                               |  |  |
|---|----------------|-------------------------|---------------------|------|---------------|-------------------------------|--|--|
| Chemical or Constituent (and reporting units)                                       | Sample<br>Date | Level<br>Detected       | Range of Detections | SMCL | PHG<br>(MCLG) | Typical Source of Contaminant |  |  |
|   |                | No Results<br>to Report |                     |      |               |                               |  |  |

<sup>\*</sup>Any violation of an AL, MCL, MRDL, or TT is asterisked. Additional information regarding the violation is provided on the next page.

## Additional General Information on Drinking Water

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that the water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the U.S. EPA's Safe Drinking Water Hotline (1-800-426-4791).

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. U.S. EPA/Centers for Disease Control (CDC) guidelines on appropriate means to lessen the risk of infection by *Cryptosporidium* and other microbial contaminants are available from the Safe Drinking Water Hotline.

If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. The Eks Lodge system is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline or at http://www.epa.gov/lead.

Nitrate as Nitrogen in drinking water at levels above 10 mg/L is a health risk for infants of less than six months of age. Such nitrate levels in drinking water can interfere with the capacity of the infant's blood to carry oxygen, resulting in serious illness; symptoms include shortness of breath and blueness of the skin. Nitrate-N levels above 10 mg/L may also affect the ability of the blood to carry oxygen in other individuals, such as pregnant women and those with specific enzyme deficiencies. If you are caring for an infant, or you are pregnant, you should ask advice from your health care provider.

# Summary Information for Violation of an MCL, MRDL, AL, TT, or Monitoring and Reporting Requirements

In 2022, 1,2,3-Trichloropropane (1,2,3-TCP) was detected at the well above the 0.005 ug/L maximum contaminant (allowable) limit. Some people who drink water containing 1,2,3-TCP in excess of the MCL over many years may have an increased risk of getting cancer. Additional testing is scheduled to to determine if remedial action is necessary. No action to lower 1,2,3-TCP has been required by the State at this time.

## **Vulnerability Assessment Summary**

A source water assessment was conducted for the well of Elks Lodge 1282 water system in January, 2009. The source is considered most vulnerable to the following activities associated with contaminants detected in the water supply: fertilizer/pesticide/herbicide application, and septic systems - low density. The source is considered most vulnerable to the following activities not associated with any detected contaminants: injection wells/dry wells/sumps.

Although nitrates have been detected in this source, the levels have been below the MCL (maximum contaminant level). Detection of nitrates may be due to the application of fertilizers containing nitrogen. This source is located in a predominantly agricultural area were the use of fertilizers is common. Nitrates may also be prevelant due to onsite sewage disposal systems. Nitrate levels for this source are monitored through quarterly water sampling. Arsenic has been detected below the MCL in this source. The presence of arsenic may be due to the erosion of natural deposits, waste products resulting from glass or electronics manufacturing, and routine pesticide use. The source is currently in compliance with State Standards. For more information regarding the assessment summary, contact: Sam Hedge at: (209) 406-6069.