2022 Consumer Confidence Report

Water System Information

Water System Name: Bayer Research & Development Services (BRDS-SJB) San Juan Bautista

Report Date: May 23, 2023

Type of Water Source(s) in Use: Groundwater – Well 01

Name and General Location of Source(s): PWS CA3500804_001_001 located at 500 Lucy Brown Lane, San Juan Bautista, CA 95045

Drinking Water Source Assessment Information: According to the Drinking Water Source Assessment and Protection (DWSAP) Program performed by the San Benito County Department of Health Services in September 2001, the source is considered most vulnerable to the following activities associated with contaminants detected in the water supply: Crops, irrigated: Berries, hops, mint, orchards, sod, greenhouses, fertilizer, Pesticide/Herbicide Application, Septic systems - low density [<1/acre]. The source is considered most vulnerable to the following activities not associated with any detected contaminants: Pesticide/fertilizer/petroleum storage & transfer areas Research laboratories, Wells - Agricultural/ Irrigation. A copy of the complete assessment is available for review at Bayer Research and Development Services LLC - 500 Lucy Brown Lane, San Juan Bautista, CA 95405 or, the State Water Resources Control Board's Division of Drinking Water – District 05 – 1 Lower Ragsdale Drive, Bldg 1, Suite 120, Monterey, CA 93940. Please contact BRDS-SJB to schedule appointment to review.

Time and Place of Regularly Scheduled Board Meetings for Public Participation: Not Applicable

For More Information, Contact: Bernice Pettit (530) 267-6082

About This Report

We test the drinking water quality for many constituents as required by state and federal regulations. This report shows the results of our monitoring for the period of January 1 to December 31, 2022 and may include earlier monitoring data.

Importance of This Report Statement in Five Non-English Languages (Spanish, Mandarin, Tagalog, Vietnamese, and Hmong)

Language in Spanish: Este informe contiene información muy importante sobre su agua para beber. Favor de comunicarse Bayer Research & Development Service LLC a 500 Lucy Brown Lane, San Juan Bautista, CA 95045 para asistirlo en español.

Language in Mandarin: 这份报告含有关于您的饮用水的重要讯息。请用以下地址和电话联系 Bayer Research & Development Services LLC 以获得中文的帮助: 500 Lucy Brown Lane, San Juan Bautista, CA 95045.

Langauge in Tagalog: Ang pag-uulat na ito ay naglalaman ng mahalagang impormasyon tungkol sa inyong inuming tubig. Mangyaring makipag-ugnayan sa Bayer Research & Development Services LLC - 500 Lucy Brown Lane, San Juan Bautista, CA 95045 para matulungan sa wikang Tagalog.

Language in Vietnamese: Báo cáo này chứa thông tin quan trọng về nước uống của bạn. Xin vui

SWS CCR Revised January 2023

lòng liên hệ Bayer Research and Development Services LLC tại 500 Lucy Brown Lane, San Juan Bautista, CA 95045 để được hỗ trợ giúp bằng tiếng Việt.

Language in Hmong: Tsab ntawv no muaj cov ntsiab lus tseem ceeb txog koj cov dej haus. Thov hu rau Bayer Research and Development Services LLC ntawm 500 Lucy Brown Lane, San Juan Bautista, CA 95045 rau kev pab hauv lus Askiv.

Terms Used in This Report

Term	Definition
Level 1 Assessment	A Level 1 assessment is a study of the water system to identify potential problems and determine (if possible) why total coliform bacteria have been found in our water system.
Level 2 Assessment	A Level 2 assessment is a very detailed study of the water system to identify potential problems and determine (if possible) why an <i>E. coli</i> MCL violation has occurred and/or why total coliform bacteria have been found in our water system on multiple occasions.
Maximum Contaminant Level (MCL)	The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible. Secondary MCLs are set to protect the odor, taste, and appearance of drinking water.
Maximum Contaminant Level Goal (MCLG)	The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs are set by the U.S. Environmental Protection Agency (U.S. EPA).
Maximum Residual Disinfectant Level (MRDL)	The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.
Maximum Residual Disinfectant Level Goal (MRDLG)	The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.
Primary Drinking Water Standards (PDWS)	MCLs and MRDLs for contaminants that affect health along with their monitoring and reporting requirements, and water treatment requirements.
Public Health Goal (PHG)	The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California Environmental Protection Agency.
Regulatory Action Level (AL)	The concentration of a contaminant which, if exceeded, triggers treatment or other requirements that a water system must follow.
Secondary Drinking Water Standards (SDWS)	MCLs for contaminants that affect taste, odor, or appearance of the drinking water. Contaminants with SDWSs do not affect the health at the MCL levels.
Treatment Technique (TT)	A required process intended to reduce the level of a contaminant in drinking water.
Variances and Exemptions	Permissions from the State Water Resources Control Board (State Board) to exceed an MCL or not comply with a treatment technique under certain conditions.
ND	Not detectable at testing limit.
Ppm	parts per million or milligrams per liter (mg/L)

Ppb	parts per billion or micrograms per liter (µg/L)
Ppt	parts per trillion or nanograms per liter (ng/L)
Ppq	parts per quadrillion or picogram per liter (pg/L)
pCi/L	picocuries per liter (a measure of radiation)

Sources of Drinking Water and Contaminants that May Be Present in Source Water

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

Contaminants that may be present in source water include:

- Microbial contaminants, such as viruses and bacteria, that may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.
- Inorganic contaminants, such as salts and metals, that can be naturally-occurring or result from urban stormwater runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.
- Pesticides and herbicides, that may come from a variety of sources such as agriculture, urban stormwater runoff, and residential uses.
- Organic chemical contaminants, including synthetic and volatile organic chemicals, that are byproducts of industrial processes and petroleum production, and can also come from gas stations, urban stormwater runoff, agricultural application, and septic systems.
- Radioactive contaminants, that can be naturally-occurring or be the result of oil and gas production and mining activities.

Regulation of Drinking Water and Bottled Water Quality

In order to ensure that tap water is safe to drink, the U.S. EPA and the State Board prescribe regulations that limit the amount of certain contaminants in water provided by public water systems. The U.S. Food and Drug Administration regulations and California law also establish limits for contaminants in bottled water that provide the same protection for public health.

About Your Drinking Water Quality

Drinking Water Contaminants Detected

Tables 1, 2, 3, 4, 5, 6, and 8 list all of the drinking water contaminants that were detected during the most recent sampling for the constituent. The presence of these contaminants in the water does not necessarily indicate that the water poses a health risk. The State Board allows us to monitor for certain contaminants less than once per year because the concentrations of these contaminants do not change frequently. Some of the data, though representative of the water quality, are more than one year old. Any violation of an AL, MCL, MRDL, or TT is asterisked. Additional information regarding the violation is provided later in this report.

Table 1. Sampling Results Showing the Detection of Coliform Bacteria

Complete if bacteria are detected.

Microbiological Contaminants	Highest No. of Detections	No. of Months in Violation	MCL	MCLG	Typical Source of Bacteria
E. coli	1	1	(a)	0	Human and animal fecal waste
Total Coliform	2	1	(a)	0	Human and animal fecal waste

⁽a) Routine and repeat samples are total coliform-positive and either is *E. coli*-positive or system fails to take repeat samples following *E. coli*-positive routine sample or system fails to analyze total coliform-positive repeat sample for *E. coli*.

Table 2. Sampling Results Showing the Detection of Lead and Copper

Complete if lead or copper is detected in the last sample set.

Lead and Copper	Sample Date	No. of Samples Collected	90 th Percentile Level Detected	No. Sites Exceeding AL	AL	PHG	No. of Schools Requesting Lead Sampling	Typical Source of Contaminant
Lead (ppb)	07/27/21	5	Non- detect	0	15	0.2	Not applicable	Internal corrosion of household water plumbing systems; discharges from industrial manufacturers; erosion of natural deposits
Copper (ppm)	07/27/21	5	0.06	0	1.3	0.3	Not applicable	Internal corrosion of household plumbing systems; erosion of natural deposits; leaching from wood preservatives

 Table 3. Sampling Results for Sodium and Hardness

Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	MCL	PHG (MCLG)	Typical Source of Contaminant
Sodium (ppm)	NONE			None	None	Salt present in the water and is generally naturally occurring

Hardness (ppm)	NONE		None	None	Sum of polyvalent
					cations present in the
					water, generally
					magnesium and
					calcium, and are
					usually naturally
					occurring

Table 4. Detection of Contaminants with a Primary Drinking Water Standard

Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	MCL [MRDL]	PHG (MCLG) [MRDLG]	Typical Source of Contaminant
Chlorine (mg/L) [MRDL = 4.0 (as Cl ₂)]	12/28/22	0.30	0.24 – 0.35	[MRDL = 4.0 (as Cl ₂)]	[MRDLG = 4 (as Cl ₂)]	Drinking water disinfectant added for treatment
Fluoride ppm	06/18/20	0.29		2.0	1	Erosion of natural deposits; water additive which promotes strong teeth; discharge from fertilizer and aluminum factories
Gross Alpha Particle Activity (pCi/L)	12/07/22	9.38	5.07 – 12.2	15	(0)	Erosion of natural deposits
*Nitrate (as Nitrogen) ppm	12/28/22	*10.26	.7.2 – 16.4	10 (as N)	10 (as N)	Runoff and leaching from fertilizer use; leaching from septic tanks and sewage; erosion of natural deposits.

Selenium	06/18/20	19		50	30	Discharge from petroleum, glass, and metal refineries; erosion of natural deposits; discharge from mines and chemical manufacturers; runoff from livestock lots (feed additive)
Total Radium PCI/L	09/06/22	0.26	ND – 0.52	5	N/A	Erosion of natural deposits.
Uranium (pCi/L)	12/07/22	5.84	2.03 –10.43	20	0.43	Erosion of natural deposits

Table 5. Detection of Contaminants with a Secondary Drinking Water Standard

Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	SMCL	PHG (MCLG)	Typical Source of Contaminant
*Specific Conductance µS/cm	06/18/20	*2200			1,600 µS/cm	Substances that form ions when in water; seawater influence

Table 6. Detection of Unregulated Contaminants

Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	Notification Level	Health Effects
NONE					

Additional General Information on Drinking Water

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that the water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the U.S. EPA's Safe Drinking Water Hotline (1-800-426-4791).

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. U.S. EPA/Centers for Disease Control (CDC)

guidelines on appropriate means to lessen the risk of infection by *Cryptosporidium* and other microbial contaminants are available from the Safe Drinking Water Hotline (1-800-426-4791).

Lead-Specific Language: If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. Bayer Research and Development Services LLC is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. Optional: If you do so, you may wish to collect the flushed water and reuse it for another beneficial purpose, such as watering plants. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline (1-800-426-4791) or at http://www.epa.gov/lead.

Additional Special Language for Nitrate, Arsenic, Lead, Radon, and *Cryptosporidium*: Nitrate in drinking water at levels above 10 mg/L is a health risk for infants of less than six months of age. Such nitrate levels in drinking water can interfere with the capacity of the infant's blood to carry oxygen, resulting in serious illness; symptoms include shortness of breath and blueness of the skin. Nitrate levels above 10 mg/L may also affect the ability of the blood to carry oxygen in other individuals, such as pregnant women and those with specific enzyme deficiencies. If you are caring for an infant, or you are pregnant, you should ask advice from your health care provider.

State Revised Total Coliform Rule (RTCR): *E. coli* was detected on a sample collected at the routine sample site on 05/04/2022 and follow up samples were positive for Total Coliform and an E. coli violation was issued on 06/02/2022. All requirements of this violation have been addressed to SWRCB DDW District 05.

Summary Information for Violation of a MCL, MRDL, AL, TT, or Monitoring and Reporting Requirement

Table 7. Violation of a MCL, MRDL, AL, TT or Monitoring Reporting Requirement

Violation	Explanation	Duration	Actions Taken to Correct Violation	Health Effects Language
-----------	-------------	----------	------------------------------------	----------------------------

Nitrogen)	The raw source - Well 01 exceeds the MCL for Nitrate (as Nitrogen)	Continuous (prior to treatment)	This water system installed a Nitrate reduction (treatment) system on 01/12/2023. This treatment system is online, operational, and has been permitted by the SWRCB DDW Dist. 05 on 04/20/2023. This treatment system has shown it is capable of reducing the Nitrates to less than 1 ppm. Weekly nitrate laboratory analysis of the production water (Post RO Sample Tap) has ranged from a low of 0.5 ppm to a high of 1.0 ppm which reflects the treatment has effectively reduced the Nitrates by approximately	Infants below the age of six months who drink water containing nitrate in excess of the MCL may quickly become seriously ill and, if untreated, may die because high nitrate levels can interfere with the capacity of the infant's blood to carry oxygen. Symptoms include shortness of breath and blueness of the skin. High nitrate levels may also affect the oxygencarrying ability of the blood of pregnant women.
-----------	--	---------------------------------------	---	--

*Specific Conductance μS/cm The test result for this analyte reflects it was over the MCL effective 12/14/2017, at 2,500 μS/cm. The test result for this analyte reflects it was over the MCL effective 12/14/2017, at 2,500 μS/cm. Ongoing since 12/14/2017. No action taken to correct MCL violation as there are no public health goals (PHGs) or maximum contaminant level goals (MCLGs) for these constituents because secondary standards are set on the basis of aesthetic concerns.	en in
---	-------

For Water Systems Providing Groundwater as a Source of Drinking Water

Table 8. Sampling Results Showing Fecal Indicator-Positive Groundwater Source Samples

Microbiological Contaminants (complete if fecal- indicator detected)	Total No. of Detections	Sample Dates	MCL [MRDL]	PHG (MCLG) [MRDLG]	Typical Source of Contaminant
E. coli	*1	05/04/22	0	(0)	Human and animal fecal waste
Enterococci	0	Monthly	TT	N/A	Human and animal fecal waste
Coliphage	0	Monthly	TT	N/A	Human and animal fecal waste

<u>Summary Information for Fecal Indicator-Positive Groundwater Source Samples, Uncorrected Significant Deficiencies, or Violation of a Groundwater TT</u>

Special Notice of Fecal Indicator-Positive Groundwater Source Sample: Yes. Well 01 had a positive for E. coli on 05/04/22

Special Notice for Uncorrected Significant Deficiencies: Not Applicable

Table 9. Violation of Groundwater TT

Violation	Explanation	Duration	Actions Taken to Correct Violation	Health Effects Language
Not Applicable				

Summary Information for Operating Under a Variance or Exemption: Not Applicable.

Summary Information for Revised Total Coliform Rule Level 1 and Level 2 Assessment Requirements

Level 1 Assessment Requirement Due to an E. coli MCL Violation:

During the past year we were required to conduct one Level 1 Assessment as we had an E. coli positive sample from the monthly routine sample site on 05/04/2022. Follow-up sample(s) on 05/05/2022, were absent for E. coli however, they were positive for Total Coliform. Follow-up samples after 05/05/2022, were absent for E. coli and Total Coliform. On 06/02/2022, an E. coli violation was issued by the SWRCB DDW District 05 and a Level 1 Assessment was required and was already submitted to SWRCB DDW District 05 on 06/01/2022.

Level 2 Assessment Requirement Due to an E. coli MCL Violation

E. coli are bacteria whose presence indicates that the water may be contaminated with human or animal wastes. Human pathogens in these wastes can cause short-term effects, such as diarrhea, cramps, nausea, headaches, or other symptoms. They may pose a greater health risk for infants, young children, the elderly, and people with severely compromised immune systems. We found *E. coli* bacteria, indicating the need to look for potential problems in water treatment or distribution. When this occurs, we are required to conduct assessment(s) identify problems and to correct any problems that were found during these assessments.

The SWRCB DDW District 05 completed a Level 2 assessment because we found E. coli in our water system. In addition, we were required to take the following corrective actions and we completed all of these actions:

A cross connection was identified near the sample tap that was positive for E. Coli and Total Coliform. The piping from Well 01 had been connected to piping from an agricultural well on the property that is used for irrigation. The connection was right before the Flume E hose bib. BRDS-SJB has identified the cross connection and on 05/19/2022, cut off the connection and disinfected the system.

Building G was connected to an unapproved source and BRDS-SJB replumbed the system so Bldg G was connected to the source on 06/15/2022.

BRDS-SJB Well 01 did not have the ability to pump to waste however, on 07/01/2022, they installed a pump to waste on the well.