2019 Consumer Confidence Report

Water System Name: FreshPoint SPWS Report Date: 08/12/2020 (Revision 1)

We test the drinking water quality for many constituents as required by state and federal regulations. This report shows the results of our monitoring for the period of January 1 to December 31, 2019 and may include earlier monitoring data.

Este informe contiene información muy importante sobre su agua para beber. Favor de comunicarse <u>FreshPoint SPWS</u> a <u>5900 N Golden State Blvd, Turlock, CA 95382</u> para asistirlo en español.

这份报告含有关于您的饮用水的重要讯息。请用以下地址和电话联系 <u>FreshPoint SPWS</u> 以获得中文的帮助: <u>5900 N</u> Golden State Blvd, Turlock, CA 95382 (209)216-0200

Ang pag-uulat na ito ay naglalaman ng mahalagang impormasyon tungkol sa inyong inuming tubig. Mangyaring makipag-ugnayan sa <u>FreshPoint SPWS</u> <u>5900 N Golden State Blvd, Turlock, CA 95382</u> o tumawag sa <u>(209)216-0200</u> para matulungan sa wikang Tagalog.

Báo cáo này chứa thông tin quan trọng về nước uống của bạn. Xin vui lòng liên hệ <u>FreshPoint SPWS</u> tại <u>5900 N Golden</u> <u>State Blvd, Turlock, CA 95382</u> để được hỗ trợ giúp bằng tiếng Việt.

Tsab ntawv no muaj cov ntsiab lus tseem ceeb txog koj cov dej haus. Thov hu rau <u>FreshPoint SPWS</u> ntawm <u>5900 N Golden</u> <u>State Blvd, Turlock, CA 95382</u> rau kev pab hauv lus Askiv.

Type of water source(s) in use: Groundwater is sourced from the unadjudicated San Joaquin Valley – Turlock Subbasin (No. 5-022.03)

Name & general location of source(s): The 2012 Well is located on the east end of parcel APN#: 045-052-034.

Drinking Water Source Assessment information: A source water assessment was completed for the site in January, 2006.

To request copies, please visit the Stanislaus County Department of Env. Resources at 3800 Cornucopia Way C, Modesto, CA

Time and place of regularly scheduled board meetings for public participation:

Ownership for the FreshPoint SPWS does
not regularly schedule open meetings regarding the public water. Contact Quality Service, Inc. with questions about the water.

For more information, contact: Quality Service, Inc. Phone: (209)838-7842

TERMS USED IN THIS REPORT

Maximum Contaminant Level (MCL): The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible. Secondary MCLs are set to protect the odor, taste, and appearance of drinking water.

Maximum Contaminant Level Goal (MCLG): The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs are set by the U.S. Environmental Protection Agency (U.S. EPA).

Public Health Goal (PHG): The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California Environmental Protection Agency.

Maximum Residual Disinfectant Level (MRDL): The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

Maximum Residual Disinfectant Level Goal (MRDLG): The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

Primary Drinking Water Standards (PDWS): MCLs and MRDLs for contaminants that affect health along with their monitoring and reporting requirements, and water treatment requirements.

Secondary Drinking Water Standards (SDWS): MCLs for contaminants that affect taste, odor, or appearance of the drinking water. Contaminants with SDWSs do not affect the health at the MCL levels.

Treatment Technique (TT): A required process intended to reduce the level of a contaminant in drinking water.

Regulatory Action Level (AL): The concentration of a contaminant which, if exceeded, triggers treatment or other requirements that a water system must follow.

Variances and Exemptions: Permissions from the State Water Resources Control Board (State Board) to exceed an MCL or not comply with a treatment technique under certain conditions.

Level 1 Assessment: A Level 1 assessment is a study of the water system to identify potential problems and determine (if possible) why total coliform bacteria have been found in our water system.

Level 2 Assessment: A Level 2 assessment is a very detailed study of the water system to identify potential problems and determine (if possible) why an *E. coli* MCL violation has occurred and/or why total coliform bacteria have been found in our water system on multiple occasions.

ND: not detectable at testing limit

ppm: parts per million or milligrams per liter (mg/L)

ppb: parts per billion or micrograms per liter (μg/L)

ppt: parts per trillion or nanograms per liter (ng/L)

ppq: parts per quadrillion or picogram per liter (pg/L)

pCi/L: picocuries per liter (a measure of radiation)

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

Contaminants that may be present in source water include:

- *Microbial contaminants*, such as viruses and bacteria, that may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.
- *Inorganic contaminants*, such as salts and metals, that can be naturally-occurring or result from urban stormwater runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.
- Pesticides and herbicides, that may come from a variety of sources such as agriculture, urban stormwater runoff, and residential uses.
- Organic chemical contaminants, including synthetic and volatile organic chemicals, that are byproducts of industrial processes and petroleum production, and can also come from gas stations, urban stormwater runoff, agricultural application, and septic systems.
- Radioactive contaminants, that can be naturally-occurring or be the result of oil and gas production and mining activities.

In order to ensure that tap water is safe to drink, the U.S. EPA and the State Board prescribe regulations that limit the amount of certain contaminants in water provided by public water systems. The U.S. Food and Drug Administration regulations and California law also establish limits for contaminants in bottled water that provide the same protection for public health.

Tables 1, 2, 3, 4, 5, and 6 list all of the drinking water contaminants that were detected during the most recent sampling for the constituent. The presence of these contaminants in the water does not necessarily indicate that the water poses a health risk. The State Board allows us to monitor for certain contaminants less than once per year because the concentrations of these contaminants do not change frequently. Some of the data, though representative of the water quality, are more than one year old. Any violation of an AL, MCL, MRDL, or TT is asterisked. Additional information regarding the violation is provided later in this report.

TABLE 1 – SAMPLING RESULTS SHOWING THE DETECTION OF COLIFORM BACTERIA							
Microbiological Contaminants (complete if bacteria detected)	Highest No. of Detections	No. of Months in Violation	MCL	MCLG	Typical Source of Bacteria		
Total Coliform Bacteria (state Total Coliform Rule)	(In a month)	0	1 positive monthly sample ^(a)	0	Naturally present in the environment		
Fecal Coliform or <i>E. coli</i> (state Total Coliform Rule)	(In the year)	0	A routine sample and a repeat sample are total coliform positive, and one of these is also fecal coliform or <i>E. coli</i> positive		Human and animal fecal waste		
E. coli (federal Revised Total Coliform Rule)	(In the year)	0	(b)	0	Human and animal fecal waste		

⁽a) Two or more positive monthly samples is a violation of the MCL

⁽b) Routine and repeat samples are total coliform-positive and either is *E. coli*-positive or system fails to take repeat samples following *E. coli*-positive routine sample or system fails to analyze total coliform-positive repeat sample for *E. coli*.

TABLE 2 – SAMPLING RESULTS SHOWING THE DETECTION OF LEAD AND COPPER								
Lead and Copper (complete if lead or copper detected in the last sample set)	Sample Date	No. of Samples Collected	90 th Percentile Level Detected	No. Sites Exceeding AL	AL	PHG	No. of Schools Requesting Lead Sampling	Typical Source of Contaminant
Lead (ppb)	2017	5	0	0	15	0.2	FreshPoint SPWS does not provide water to any school sites.	Internal corrosion of household water plumbing systems; discharges from industrial manufacturers; erosion of natural deposits
Copper (ppm)	2017	5	0.14	0	1.3	0.3	Not applicable	Internal corrosion of household plumbing systems; erosion of natural deposits; leaching from wood preservatives

		– SAMPLING I		SUDIUM A		NESS
Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	MCL	PHG (MCLG)	Typical Source of Contaminant
Sodium (ppm)	08/19/2014	25	N/A	None	None	Salt present in the water and is generally naturally occurring
Hardness (ppm)	08/19/2014	66.4	N/A	None	None	Sum of polyvalent cations present in the water, generally magnesium and calcium, and are usually naturally occurring
TABLE 4 – DET	TECTION O	F CONTAMINA	ANTS WITH A	PRIMARY 1	DRINKING	WATER STANDARD
Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	MCL [MRDL]	PHG (MCLG) [MRDLG]	Typical Source of Contaminant
Arsenic (μg/L)	2019 (Weekly)	6.17	0 - 14	10	0.004	Erosion of natural deposits; runoff from orchards; glass and electronics production wastes
Chromium, Total (µg/L)	08/25/2017	9.2	N/A	50	(100)	Discharge from steel and pulp mills and chrome plating; erosion of natural deposits
Gross Alpha Particle Activity (pCi/L)	2017 (Quarterly)	1.5	0.515 - 3.000	15	(0)	Erosion of natural deposits
Nitrate, as Nitrogen (mg/L)	08/21/2019	1.5	N/A	10	10	Runoff and leaching from fertilizer use; leaching from septic tanks and sewage; erosion of natural deposits
Nitrate + Nitrite, as N (mg/L)	08/25/2017	1.8	N/A	10	10	Runoff and leaching from fertilizer use; leaching from septic tanks and sewage; erosion of natural deposits
Total Radium (pCi/L)	2017 (Quarterly)	0.426	0.11 – 1.000	5	N/A	Erosion of natural deposits
Uranium (pCi/L)	2017 (Quarterly)	0.782	0.497 - 1	20	0.43	Erosion of natural deposits
Chlorine (mg/L)	2019 (Monthly)	1.09	0.04 - 1.81	[MRDL = 4.0 (as Cl2)]	[MRDLG = 4 (as Cl2)]	Drinking water disinfectant added for treatment
Total Trihalomethanes, TTHM (μg/L)	08/21/2019	2	2 - 2	80	N/A	Byproduct of drinking water disinfection
Sum of 5 Haloacetic Acids, HAA5 (μg/L)	08/21/2019	0	0-0	60	N/A	Byproduct of drinking water disinfection
TABLE 5 – DETE	ECTION OF	CONTAMINA	NTS WITH A <u>S</u> I	ECONDARY	Y DRINKIN	G WATER STANDARD
Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	SMCL	PHG (MCLG)	Typical Source of Contaminant
Chloride (mg/L)	08/19/2014	6	N/A	500	No PHG	Runoff/leaching from natural deposits; seawater influence
Specific Conductance (μS/cm)	08/19/2014	260	N/A	1,600	No PHG	Substances that form ions when in water; seawater influence
Sulfate (mg/L)	08/19/2014	4.7	N/A	500	No PHG	Runoff/leaching from natural deposits; industrial wastes
Total Dissolved Solids (mg/L)	08/19/2014	210	N/A	1,000	No PHG	Runoff/leaching from natural deposits
	TABLE (6 – DETECTION	N OF UNREGU	LATED CO	NTAMINA	NTS
Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	Notificat	tion Level	Health Effects Language
Hexavalent Chromium (μg/L)	08/25/2017	9.2	N/A	(FORMERLY) 1 μg/L		Chromium-6 exposures resulted in developmental and reproductive effects in rats
Vanadium (µg/L)	08/25/2017	55	N/A	5	50	Vanadium exposures resulted in developmental and reproductive effects in rats.

Additional General Information on Drinking Water

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that the water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the U.S. EPA's Safe Drinking Water Hotline (1-800-426-4791).

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. U.S. EPA/Centers for Disease Control (CDC) guidelines on appropriate means to lessen the risk of infection by *Cryptosporidium* and other microbial contaminants are available from the Safe Drinking Water Hotline (1-800-426-4791).

Lead-Specific Language: If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. *FreshPoint SPWS* is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. *[OPTIONAL:* If you do so, you may wish to collect the flushed water and reuse it for another beneficial purpose, such as watering plants.] If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline (1-800-426-4791) or at http://www.epa.gov/lead.

Arsenic-Specific Language: Be advised that the raw water that we source is required to be treated for arsenic. We have a full-scale arsenic treatment plant that filters water intended for domestic uses. While your drinking water meets the federal and state standard for arsenic, it does contain low levels of arsenic. The arsenic standard balances the current understanding of arsenic's possible health effects against the cost of removing arsenic from drinking water. The U.S. Environmental Protection Agency continues to research the health effects of low levels of arsenic, which is a mineral known to cause cancer in humans at high concentrations and is linked to other health effects such as skin damage and circulatory problems.

Source Water Assessment Vulnerability Summary

As a consumer, you have a right to know what's going on with the quality and nature of the water you receive. You will be notified if the analytical monitoring program shows the water does not meet a primary state standard; the summary below is not intended to raise concerns about the water supply, nor is it to say that the activities that have been identified will cause the source to be contaminated now or in the future. This assessment is used to inform the water system about potential hazards that could influence the groundwater quality so that management practices may be employed or bolstered to protect the water that we provide you. [NOTE: The following summary of vulnerability is based on an assessment made in January, 2006. Some information may no longer be currently applicable.]

A drinking water source assessment was completed for the FreshPoint SPWS in January of 2006. Stanislaus County completed the report. The primary supply for the system was found to be most vulnerable to the following activities associated with contaminants detected in the water supply:

• Fertilizer/Pesticide/Herbicide Application

• Septic systems – low density [<1/acre]

The source is considered most vulnerable to the following activities that are not associated with any of the contaminants that have been detected:

• Automobile – Gas Stations

Nitrates have been detected in this water source. The level was below the Maximum Contaminant Level (MCL) of 10 mg/L. Nitrates are typically associated with onsite sewage disposal, as well as the use of fertilizers containing nitrogen. This general area has historically been used for agricultural purposes. There is low-density activity of onsite sewage disposal in the first two Time-of-Travel (TOT) zones. In the third TOT zone, there is high-density activity of onsite sewage disposal. Recent water quality analyses on file indicate that this source is currently in compliance with State Standards. However, the source is still considered to be vulnerable to activities occurring within proximity.

Summary Information for Violation of a MCL, MRDL, AL, TT, or Monitoring and Reporting Requirement

VIOLATION OF A MCL, MRDL, AL, TT, OR MONITORING AND REPORTING REQUIREMENT							
Violation	Explanation	Duration	Actions Taken to Correct the Violation Health Effect Language				
N/A	N/A	N/A	N/A	N/A			
N/A	N/A	N/A	N/A	N/A			

For Water Systems Providing Groundwater as a Source of Drinking Water

TABLE 7 – SAMPLING RESULTS SHOWING FECAL INDICATOR-POSITIVE GROUNDWATER SOURCE SAMPLES							
Microbiological Contaminants (complete if fecal-indicator detected) Total No. of Detections Sample Dates MCL [MRDL] MCL (MCLG) [MRDLG] Typical Source of Contamination					Typical Source of Contaminant		
E. coli	(In the year)	2019 (Monthly)	0	(0)	Human and animal fecal waste		
Enterococci	0 (In the year)	NT	TT	N/A	Human and animal fecal waste		
Coliphage	(In the year)	NT	TT	N/A	Human and animal fecal waste		

Summary Information for Fecal Indicator-Positive Groundwater Source Samples, Uncorrected Significant Deficiencies, or Groundwater TT

SPECIAL NOTICE OF FECAL INDICATOR-POSITIVE GROUNDWATER SOURCE SAMPLE

Water sampling for the FreshPoint SPWS <u>DID NOT</u> show presence of Total Coliform or E. Coli bacteria in the groundwater or distribution system during the 2019 year. As such, no Level I or Level II (sanitary) Assessments were required to be completed, and there was no Groundwater TT required.

SPECIAL NOTICE FOR UNCORRECTED SIGNIFICANT DEFICIENCIES

The FreshPoint SPWS <u>has not</u> received notice from the State Water Board of any significant deficiency; at this time, it is our understanding that groundwater sampling has shown absence for bacteria and that there has not been a violation of a treatment technique. Therefore, no special notice can be given as there are no significant deficiencies that have gone uncorrected to our knowledge.

VIOLATION OF GROUNDWATER TT

TT Violation	Explanation	Duration	Actions Taken to Correct the Violation	Health Effects Language
N/A	N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A	N/A