

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025

Water System Information

Water System Name:	Silver Oak Wine Cellars, LLC
Water System Classification:	Non-transient Non-Community Water System
Water System No:	CA 49-01374
Name of Source	Winery Well (Well # 003)
Source ID #	CA 49-01374-004-004
Type of Water Source in Use	Ground Water Well
Source Location	7300 Highway 128, Healdsburg, Ca 95448

Drinking Water Source Assessment Information:

An assessment of the drinking water source(s) for Silver Oak Wine Cellars was completed on April 28, 2025. A copy of the complete assessment, including analysis reports, are available at 7300 Highway 128, Healdsburg, Ca 95448. A copy of the assessment may be requested by contacting Tasha Hart, Silver Oak's Water System Representative at (707) 942-7071 or thart@silveroak.com.

Drinking Water Analysis Information:

Analysis has been conducted throughout the year by Brelje & Race Laboratory. Copies may be obtained by contacting Brelje & Race at 425 S. E Street, Santa Rosa, California or (707) 544-8807.

Time and place of regularly scheduled board meetings for public participation:

The privately owned water system does not require regularly scheduled board meetings for public participation.

For more information, contact: Tasha Hart

Phone: (707) 942-7071

Email thart@silveroak.com

About This Report

The drinking water quality for many constituents is tested as required by state and federal regulations. This report shows the monitoring results for the period of January 1 to December 31, 2023 and may include earlier monitoring data.

Importance of This Report Statement in Five Non-English Languages (Spanish, Mandarin, Tagalog, Vietnamese, and Hmong)

Language in Spanish: Este informe contiene información muy importante sobre el agua potable de este sistema. Favor de comunicarse Silver Oak Wine Cellars, LLC a (707) 942-7071 para asistirlo en español.

Language in Mandarin: 这份报告含有关于您的饮用水的重要讯息。请用以下地址和电话联系 Silver Oak Wine Cellars, LLC 以获得中文的帮助: (707) 942-7071.

Language in Tagalog: Ang pag-uulat na ito ay naglalaman ng mahalagang impormasyon tungkol sa inyong inuming tubig. Mangyaring makipag-ugnayan sa Silver Oak Wine Cellars, LLC o tumawag sa (707) 942-7071 para matulungan sa wikang Tagalog.

Language in Vietnamese: Báo cáo này chứa thông tin quan trọng về nước uống của bạn. Xin vui lòng liên hệ Silver Oak Wine Cellars, LLC tại (707) 942-7071 để được hỗ trợ giúp bằng tiếng Việt.

Language in Hmong: Tsab ntawv no muaj cov ntsiab lus tseem ceeb txog koj cov dej haus. Thov hu rau Silver Oak Wine Cellars, LLC ntawm (707) 942-7071 rau kev pab hauv lus Askiv.

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025

Terms Used in This Report

Term	Definition
Level 1 Assessment	A Level 1 assessment is a study of the water system to identify potential problems and determine (if possible) why total coliform bacteria have been found in our water system.
Level 2 Assessment	A Level 2 assessment is a very detailed study of the water system to identify potential problems and determine (if possible) why an <i>E. coli</i> MCL violation has occurred and/or why total coliform bacteria have been found in our water system on multiple occasions.
Maximum Contaminant Level (MCL)	The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible. Secondary MCLs are set to protect the odor, taste, and appearance of drinking water.
Maximum Contaminant Level Goal (MCLG)	The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs are set by the U.S. Environmental Protection Agency (U.S. EPA).
Maximum Residual Disinfectant Level (MRDL)	The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.
Maximum Residual Disinfectant Level Goal (MRDLG)	The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.
Primary Drinking Water Standards (PDWS)	MCLs and MRDLs for contaminants that affect health along with their monitoring and reporting requirements, and water treatment requirements.
Public Health Goal (PHG)	The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California Environmental Protection Agency.
Regulatory Action Level (AL)	The concentration of a contaminant which, if exceeded, triggers treatment or other requirements that a water system must follow.
Secondary Drinking Water Standards (SDWS)	MCLs for contaminants that affect taste, odor, or appearance of the drinking water. Contaminants with SDWSs do not affect the health at the MCL levels.
Treatment Technique (TT)	A required process intended to reduce the level of a contaminant in drinking water.
Variances and Exemptions	Permissions from the State Water Resources Control Board (State Board) to exceed an MCL or not comply with a treatment technique under certain conditions.
ND	Not detectable at testing limit.
ppm	parts per million or milligrams per liter (mg/L)
ppb	parts per billion or micrograms per liter (µg/L)
ppt	parts per trillion or nanograms per liter (ng/L)
ppq	parts per quadrillion or picogram per liter (pg/L)
pCi/L	picocuries per liter (a measure of radiation)

Sources of Drinking Water and Contaminants that May Be Present in Source Water

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

Contaminants that may be present in source water include:

- Microbial contaminants, such as viruses and bacteria, that may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.
- Inorganic contaminants, such as salts and metals, that can be naturally-occurring or result from urban stormwater runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.
- Pesticides and herbicides, that may come from a variety of sources such as agriculture, urban stormwater runoff, and residential uses.
- Organic chemical contaminants, including synthetic and volatile organic chemicals, that are byproducts of industrial processes and petroleum production, and can also come from gas stations, urban stormwater runoff, agricultural application, and septic systems.
- Radioactive contaminants, that can be naturally-occurring or be the result of oil and gas production and mining activities.

Regulation of Drinking Water and Bottled Water Quality

In order to ensure that tap water is safe to drink, the U.S. EPA and the State Board prescribe regulations that limit the amount of certain contaminants in water provided by public water systems. The U.S. Food and Drug Administration regulations and California law also establish limits for contaminants in bottled water that provide the same protection for public health.

About Your Drinking Water Quality

Drinking Water Contaminants Detected

Tables 1, 2, 3, 4, 5, 6, and 8 list all of the drinking water contaminants that were detected during the most recent sampling for the constituent. The presence of these contaminants in the water does not necessarily indicate that the water poses a health risk. The State Board allows us to monitor for certain contaminants less than once per year because the concentrations of these contaminants do not change frequently. Some of the data, though representative of the water quality, are more than one year old. Any violation of an AL, MCL, MRDL, or TT is asterisked. Additional information regarding the violation is provided later in this report.

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025

Table 1. Sampling Results Showing the Detection of Coliform Bacteria

Complete if bacteria are detected.

Microbiological Contaminants	Highest No. of Detections	No. of Months in Violation	MCL	MCLG	Typical Source of Bacteria
Total Coliform Bacteria (State Total Coliform Rule)	(In a month) 0	[Enter No.] 0	1 positive monthly sample ^(a)	0	Naturally present in the environment
Fecal Coliform or <i>E. coli</i> (State Total Coliform Rule)	(In the year) [Enter No.] 0	[Enter No.] 0	A routine sample and a repeat sample are total coliform positive, and one of these is also fecal coliform or <i>E. coli</i> positive	None	Human and animal fecal waste
<i>E. coli</i> (Federal Revised Total Coliform Rule)	(In the year) [Enter No.] 0	[Enter No.] 0	(b)	0	Human and animal fecal waste

(a) Two or more positive monthly samples is a violation of the MCL

(b) Routine and repeat samples are total coliform-positive and either is *E. coli*-positive or system fails to take repeat samples following *E. coli*-positive routine sample or system fails to analyze total coliform-positive repeat sample for *E. coli*.

Table 2. Sampling Results Showing the Detection of Lead and Copper

Complete if lead or copper is detected in the last sample set.

Lead and Copper	Sample Date	No. of Samples Collected	90 th Percentile Level Detected	No. Sites Exceeding AL	AL	PHG	No. of Schools Requesting Lead Sampling	Typical Source of Contaminant
Lead (ppb)	[Enter Date] 07/02/2024	[Enter No.] 10	[Enter No.] <0.0050 0 mg/L	[Enter No.] 0	15	0.2	[Enter No.] 0	Internal corrosion of household water plumbing systems; discharges from industrial manufacturers; erosion of natural deposits
Copper (ppm)	[Enter Date] 07/02/2024	[Enter No.] 10	[Enter No.] 0.7900 mg/L	[Enter No.] 0	1.3	0.3	Not applicable	Internal corrosion of household plumbing systems; erosion of natural deposits; leaching from wood preservatives

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025

Table 3. Sampling Results for Sodium and Hardness

Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	MCL	PHG (MCLG)	Typical Source of Contaminant
Sodium (ppm)	[Enter Date] 1/19/2023	[Enter No.] 26ppm	[Enter Range] 1.0	None	None	Salt present in the water and is generally naturally occurring
Hardness (ppm)	[Enter Date] 1/19/2023	[Enter No.] 240ppm	[Enter Range] 5	None	None	Sum of polyvalent cations present in the water, generally magnesium and calcium, and are usually naturally occurring

Table 4. Detection of Contaminants with a Primary Drinking Water Standard

Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	MCL [MRDL]	PHG (MCLG) [MRDLG]	Typical Source of Contaminant
Fluoride (F) (Natural Source)	1/19/2023	0.22 mg/L	0.100	2	1	Erosion of natural deposits; water additive which promotes strong teeth; discharge from fertilizer and aluminum factories
Combined Radium 226 & 228	10/10/13	0.0800 pCi/L	0	5	(0)3	Erosion of natural deposits
Nitrate (as Nitrogen; N)	4/17/2024	2.2 mg/L	0.4	10	10	Runoff and leaching from fertilizer use; leaching from septic tanks and sewage; erosion of natural deposits.
Turbidity	1/19/2023	0.15 NTU	0.1 NTU	TT = 2	N/A	Soil runoff

¹Turbidity is a measure of the cloudiness of the water. Monitoring Turbidity is valuable indicator when determining water quality. High turbidity can hinder the effectiveness of disinfectants. ²Refer to turbidity limits established by the State Water Board.

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025

Nitrate (Table 4) Special Language for Community Water Systems:

The Silver Oak Wine Cellars water system did not detect above levels for the following constituents: Nitrate, Arsenic, Lead, or Randon. However, Nitrate is present at a low level of 2.2 ppm and does meet the drinking water federal and state standards. Nitrate in drinking water at levels above 10 mg/L is a health risk for infants of less than six months of age. Such nitrate levels in drinking water can interfere with the capacity of the infant's blood to carry oxygen, resulting in serious illness; symptoms include shortness of breath and blueness of the skin. Nitrate levels above 10 mg/L may also affect the ability of the blood to carry oxygen in other individuals, such as pregnant women and those with specific enzyme deficiencies. If you are caring for an infant, or you are pregnant, you should ask advice from your health care provider.

Table 5. Detection of Contaminants with a Secondary Drinking Water Standard

Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	SMCL	PHG (MCLG)	Typical Source of Contaminant
Total Dissolved Solids	1/19/2023	320 ppm	0.00	1,000	N/A	Soil Runoff
Specific Conductance	10/10/13	500 μ S/cm	0.00	1,600	N/A	Substances that form ions when in water; seawater influence
Chloride	1/19/2023	9.6 ppm	0.00	500	N/A	Runoff/leaching from natural deposits; seawater influence
Sulfate	1/19/2023	34.0 ppm	0.500	500	N/A	Runoff/leaching from natural deposits; industrial wastes
Turbidity	10/10/13	1.9 NTU	0.1 NTU	TT = 2	N/A	Soil runoff

1Turbidity is a measure of the cloudiness of the water. Monitoring Turbidity is valuable indicator when determining water quality. High turbidity can hinder the effectiveness of disinfectants. 2Refer to turbidity limits established by the State Water Board.

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025

Table 6. Detection of Unregulated Contaminants

Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	Notification Level	Health Effects Language
Boron	10/10/13	0.091 ppm	0.100 ppm	1 ppm	Boron exposures resulted in decreased fetal weight (developmental effects) in newborn rats.
Vanadium	10/10/13	4.3 ppb	3.0 ppb	50 ppb	Vanadium exposures resulted in developmental and reproductive effects in rats.

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025

Additional General Information on Drinking Water

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that the water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the U.S. EPA's Safe Drinking Water Hotline (1-800-426-4791).

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. U.S. EPA/Centers for Disease Control (CDC) guidelines on appropriate means to lessen the risk of infection by *Cryptosporidium* and other microbial contaminants are available from the Safe Drinking Water Hotline (1-800-426-4791).

Lead-Specific Language: If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. Silver Oak Wine Cellars, LLC is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. [Optional: If you do so, you may wish to collect the flushed water and reuse it for another beneficial purpose, such as watering plants.] If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline (1-800-426-4791) or at <http://www.epa.gov/lead>.

Federal Revised Total Coliform Rule (RTCR): *This Consumer Confidence Report (CCR) reflects changes in drinking water regulatory requirements during 2016. All water systems are required to comply with the state Total Coliform Rule. Effective April 1, 2016, all water systems are also required to comply with the federal Revised Total Coliform Rule. The new federal rule maintains the purpose to protect public health by ensuring the integrity of the drinking water distribution system and monitoring for the presence of microbials (i.e., total coliform and E. coli bacteria). The U.S. EPA anticipates greater public health protection as the new rule requires water systems that are vulnerable to microbial contamination to identify and fix problems. Water systems that exceed a specified frequency of total coliform occurrences are required to conduct an assessment to determine if any sanitary defects exist. If found, these must be corrected by the water system.*

Summary Information for Violation of a MCL, MRDL, AL, TT, or Monitoring and Reporting Requirement

Table 7. Violation of a MCL, MRDL, AL, TT or Monitoring Reporting Requirement

Chemical or Constituent	N/A
Violation	
Explanation	
Duration	
Actions Taken to Correct the Violation	
Health Effects Language	
<i>Note: MCL = Maximum Contaminant Level</i>	

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025
For Water Systems Providing Groundwater as a Source of Drinking Water

Table 8. Sampling Results Showing Fecal Indicator-Positive Groundwater Source Samples

Microbiological Contaminants (complete if fecal-indicator detected)	Total No. of Detections	Sample Dates	MCL [MRDL]	PHG (MCLG) [MRDLG]	Typical Source of Contaminant
<i>E. coli</i>	None detected		0	(0)	Human and animal fecal waste
Enterococci	None detected		TT	N/A	Human and animal fecal waste
Coliphage	None detected		TT	N/A	Human and animal fecal waste

Summary Information for Fecal Indicator-Positive Groundwater Source Samples, Uncorrected Significant Deficiencies, or Violation of a Groundwater TT

Special Notice of Fecal Indicator-Positive Groundwater Source Sample: None detected

Special Notice for Uncorrected Significant Deficiencies: None detected

Table 9. Violation of Groundwater TT

Violation	Explanation	Duration	Actions Taken to Correct Violation	Health Effects Language
None detected				

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025
For Systems Providing Surface Water as a Source of Drinking Water

Table 10. Sampling Results Showing Treatment of Surface Water Sources

Treatment Technique ^(a) (Type of approved filtration technology used)	N/A this system does not use Surface water
Turbidity Performance Standards ^(b) (that must be met through the water treatment process)	<p>Turbidity of the filtered water must:</p> <p>1 – Be less than or equal to [Enter Turbidity Performance Standard to Be Less Than or Equal to 95% of Measurements in a Month] NTU in 95% of measurements in a month.</p> <p>2 – Not exceed [Enter Turbidity Performance Standard Not to Be Exceeded for More Than Eight Consecutive Hours] NTU for more than eight consecutive hours.</p> <p>3 – Not exceed [Enter Turbidity Performance Standard Not to Be Exceeded at Any Time] NTU at any time.</p>
Lowest monthly percentage of samples that met Turbidity Performance Standard No. 1.	[Enter No.]
Highest single turbidity measurement during the year	[Enter No.]
Number of violations of any surface water treatment requirements	[Enter No.]

(a) A required process intended to reduce the level of a contaminant in drinking water.

(b) Turbidity (measured in NTU) is a measurement of the cloudiness of water and is a good indicator of water quality and filtration performance. Turbidity results which meet performance standards are considered to be in compliance with filtration requirements.

Summary Information for Violation of a Surface Water TT

Table 11. Violation of Surface Water TT

Violation	Explanation	Duration	Actions Taken to Correct Violation	Health Effects Language
	N/A this system does not use Surface water			

Summary Information for Operating Under a Variance or Exemption

N/A

SILVER OAK WINE CELLARS | 2024 CONSUMER CONFIDENCE REPORT

Water System # CA 49-01374 | Address 7300 Highway 128, Healdsburg, CA 95448 | Report Date April 28, 2025

Summary Information for Federal Revised Total Coliform Rule Level 1 and Level 2 Assessment Requirements

Level 1 or Level 2 Assessment Requirement not Due to an *E. coli* MCL Violation

Coliforms are bacteria that are naturally present in the environment and are used as an indicator that other, potentially harmful, waterborne pathogens may be present or that a potential pathway exists through which contamination may enter the drinking water distribution system. If found coliforms indicating the need to look for potential problems in water treatment or distribution. When this occurs, we are required to conduct assessment(s) to identify problems and to correct any problems that were found during these assessments.

During the past year we were required to conduct 0 Level 1 assessment(s). In addition, we were required to take no corrective actions.

During the past year 0 Level 2 assessments were required to be completed for our water system. In addition, we were required to take 0 corrective actions.

Level 2 Assessment Requirement Due to an *E. coli* MCL Violation

E. coli are bacteria whose presence indicates that the water may be contaminated with human or animal wastes. Human pathogens in these wastes can cause short-term effects, such as diarrhea, cramps, nausea, headaches, or other symptoms. They may pose a greater health risk for infants, young children, the elderly, and people with severely-compromised immune systems. If found *E. coli* bacteria, indicating the need to look for potential problems in water treatment or distribution. When this occurs, we are required to conduct assessment(s) identify problems and to correct any problems that were found during these assessments.

We were required to complete 0 Level 2 assessment because we found no *E. coli* in our water system. In addition, we were not required to corrective actions.